

Inspection Photos

October 20, 2022

Operator: EOG Resources Inc - #27742

Location ID: 313129

Location Name: GEHRIG UNIT-612N94W/23SWNW

Inspection Document #: 702800854

Moffat County, CO

SWNW Section 23 T12N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: GEHRIG UNIT-612N94W/23SWNW

Location ID: 313129



Photo 1. Photo taken to the east of the Location shows the access road is dominated by bare ground and kochia, an annual undesirable plant species/weed.



Photo 2. Photo taken from the east shows an overview of the Location. The species shown colonizing the Location in this photo are kochia, annual wheatgrass (annual undesirable plant species) and halogeton (noxious weed). Native shrubs are also present towards the center of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800854

Inspection Photos

Location Name: GEHRIG UNIT-612N94W/23SWNW

Location ID: 313129



Photo 3. Photo taken from the center of the Location shows an overview to the north. Native shrubs (saltbush spp., rabbitbrush, greasewood) are common. Grasses which appear to have been seeded (western wheatgrass) are rare. The plant community is dominated by annual weeds.



Photo 4. Photo taken from the center of the Location shows an overview to the east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800854

Inspection Photos

Location Name: GEHRIG UNIT-612N94W/23SWNW

Location ID: 313129



Photo 5. Photo taken from the center of the Location shows an overview to the south.



Photo 6. Photo taken from the center of the Location shows an overview to the west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800854

Inspection Photos
Location Name: GEHRIG UNIT-612N94W/23SWNW
Location ID: 313129



Photo 7. Photo taken from the west of the Location shows small patches of western wheatgrass, a native perennial grass which appears to have been seeded, but is rare and largely unsuccessful. All other herbaceous species pictured are noxious weeds and undesirable plant species.



Photo 8. Photo taken from the west shows the contrast between the disturbed Location (left) and adjacent reference area (right).

Inspection Photos

Location Name: GEHRIG UNIT-612N94W/23SWNW

Location ID: 313129



Photo 9. Photos show examples of trash/debris on Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800854

Inspection Photos
Location Name: GEHRIG UNIT-612N94W/23SWNW
Location ID: 313129



Photo 10. Photo taken to the northwest shows the reference area vegetation community.

