

Inspection Photos
Location Name: Bradbury 32-24
Location ID: 320178



Photo #1 Tank.

Photo #2 Tank missing bull plug.

Inspection Photos
Location Name: Bradbury 32-24
Location ID: 320178



Photo #3 Separator.

Photo #4 Well Head, unused equipment.

Inspection Photos
Location Name: Bradbury 32-24
Location ID: 320178



Photo #5 Unused equipment and trash.

Photo #6 Unused equipment.