

# Interim Reclamation and Stormwater Inspection

October 19, 2022

Operator: VERDAD RESOURCES LLC #10651

Location ID: 432694

Inspection Document #: 697504291

Weld County, CO

NENE Section 35 T9N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Shull 1-35-9-60 PAD  
Location ID: 432694



**Photo 1.** Photo taken from the western interim reclamation area, facing North. Photo illustrates annual, weedy Kochia vegetation has established, which is not reflective of reference area vegetation.



**Photo 2.** Close up photo taken from Photo 1.



Inspection Photos  
Location Name: Shull 1-35-9-60 PAD  
Location ID: 432694



**Photo 3.** Photo taken from the southwestern interim reclamation area, facing South. See comments under Photo 1. Photo also illustrates some desirable native establishment- red and green grass vegetation.



**Photo 4.** Photo taken from the pit area, facing North. Pit area has established with mostly annual, weedy Kochia establishment with occasional desirable native establishment.



Inspection Photos  
Location Name: Shull 1-35-9-60 PAD  
Location ID: 432694



**Photo 5.** Photo taken from the pit area, facing West. See comments under Photo 4.



**Photo 6.** Photo taken from the pit area, facing South. See comments under Photo 4.



Inspection Photos  
Location Name: Shull 1-35-9-60 PAD  
Location ID: 432694



**Photo 7.** Photo taken from southwestern interim area, facing East. See comments under Photo 1.



**Photo 8.** Photo taken from southern interim area, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: Shull 1-35-9-60 PAD  
Location ID: 432694



**Photo 9.** Photo taken from southern interim area, facing West. Photo illustrates Canada thistle, a List B Colorado noxious weed that appears to be spreading into interim reclamation areas.



**Photo 10.** Photo taken from southeastern interim area, facing East. Photo illustrates unmanaged weeds.



Inspection Photos  
Location Name: Shull 1-35-9-60 PAD  
Location ID: 432694



**Photo 11.** Photo taken from southeastern interim area, facing West. Photo illustrates what appears to be a potential topsoil stockpile lacking vegetative growth and is not stabilized.



**Photo 12.** Photo taken from southeastern interim area, facing North. See comments under Photo 11.



Inspection Photos  
Location Name: Shull 1-35-9-60 PAD  
Location ID: 432694



**Photo 13.** Reference photo taken from the southwestern location, facing East.



**Photo 14.** Close up reference photo taken from Photo 13 illustrates desirable perennial vegetation.