

Interim Reclamation and Stormwater Inspection

October 19, 2022

Operator: VERDAD RESOURCES LLC #10651

Location ID: 429096

Inspection Document #: 697504305

Weld County, CO

Lot 4 Section 3 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Pergamos/3-11-7-60
Location ID: 429096



Photo 1. Photo taken from the northwestern interim reclamation area, facing North. Photo illustrates the establishment of mostly introduced grass species which is not reflective of reference areas.

Reference areas are to the left of the red-dashed; interim areas are to the right.



Photo 2. Photo taken from the northwestern interim reclamation area, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos/3-11-7-60
Location ID: 429096



Photo 3. Photo taken from the northern interim reclamation area, facing West. Photo illustrates bare ground with some Kochia establishment.



Photo 4. Photo taken from the northern interim reclamation, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos/3-11-7-60
Location ID: 429096



Photo 5. Photo taken from the northeastern interim reclamation area, facing East. Photo illustrates the establishment of introduced grass species within the interim reclamation areas which is not reflective of reference areas.

Reference areas are to the left of the red-dashed; interim areas are to the right.



Photo 6. Photo taken from the northeastern interim reclamation area, facing South. Photo illustrates a mix of native and introduced grass species.

Inspection Photos
Location Name: Pergamos/3-11-7-60
Location ID: 429096



Photo 7. Reference photo taken from the eastern location, facing East. Photo illustrates native grass species and no introduced grass species were observed.

