

Inspection Photogs
Location Name: Ford-Olson Unit 1
Location ID: 325156



IMG 01
Well sign



IMG 02
Location overview

WGS84 37.11496, ±16ft-107.71839
 6744 ft ±11ft
 °T SW203 ±14

DATE	CALIBRATED	ORIFICE INSPECTED	PLATE SIZE	GAS SAMPLE TAKEN	INSPECTED BY/ COMPANY
8/8/17	YES	yes s/o	0.500	yes	Aaron Estrada
3/25/18	YES	yes s/o	0.500	yes	A-Estrada

DATE	CALIBRATED YES / NO	GAS SAMPLE TYPE	BOTTLE #	ORIFICE OUT	ORIFICE IN	SPECIFIC GRAVITY	INSPECTED BY COMPANY
9/20/18	X	SPOT	#6074	0.500 (s/o) →	0.375	0.5906	Aaron Estrada
4/24/19	Y	SPOT	#4113		0.375	0.5912	Aaron Estrada
4/14/2020	Yes	SPOT	#7001		0.375	0.5908	Aaron Estrada
* ARKOMA (NEED NEW CARD) ↓ *							
4/26/21	YES	SPOT	#920		0.375 (s/c) →	0.5908	AE/SADE
4/28/21	-YES-	SPOT	#4186	0.375 (s/c)	0.375	0.5908	AE/SADE

25Oct22 11:33 Ad-hoc
 680 Sagewood Dr, Ignacio CO 81137, US © 25-Oct-22 11:33:50

IMG 03
 Calibration log