

Inspection Photos
Location Name: KRK7 #7-7 (G7E) Pad
Location ID: #323925
Inspection Date: October 25, 2022



Photo #1 – Signs and fencing at tank battery.



Photo #2 – Excavation in former tank battery area.



Inspection Photos
Location Name: KRK7 #7-7 (G7E) Pad
Location ID: #323925
Inspection Date: October 25, 2022



Photo #3 – Fenced excavation in former separator location.



Photo #4 – Fenced excavation and bermed soil stockpiles in former wellhead area.



Inspection Photos

Location Name: KRK7 #7-7 (G7E) Pad

Location ID: #323925

Inspection Date: October 25, 2022



Photo #5 – Unused equipment (process pipe) in center of pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources