


Inspection Photos
Location Name: Champlin 67 Amoco H#1
Location ID: 319925



Photo#1 Wellhead

Photo#2 Production Tanks

Inspection Photos
Location Name: Champlin 67 Amoco H#1
Location ID: 319925



Photo#3 Corrective Action: Bull Plugs Missing

Photo#4 Corrective Action: Bull Plugs Missing

Inspection Photos
Location Name: Champlin 67 Amoco H#1
Location ID: 319925



Photo#5 Separator/Gas Meter