

Inspection Photogs
Location Name: Jennie Rose 33-7-3 1
Location ID: 333710



IMG 01
Well sign

IMG 02
Location overview



IMG 03

Produced water being released at wellhead. Impacted surface material.



IMG 04

Weeds at wellhead



IMG 05
Weeds at pump jack



IMG 06
Weeds at separator



IMG 07

Unlabeled chemical container