


**Inspection Photos**  
**Near GR12 Well Pad Release**  
**Spill/Release ID: 480377**  
**Inspection Date: October 25, 2022**



**Photo #1 – 2019 COGCC GIS Online Map Viewer aerial photo depicting reported Spill/Release location (circled in black). Area observed during field inspection circled in yellow.**



**Inspection Photos**  
**Near GR12 Well Pad Release**  
**Spill/Release ID: 480377**  
**Inspection Date: October 25, 2022**



**Photo #2 – Overview of reported Spill/Release location, from access road on other side of drainage.**



**Photo #3 – View along pipeline trench.**

