

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/04/2022

Submitted Date:

10/19/2022

Document Number:

693600602

FIELD INSPECTION FORM

Loc ID 303513 Inspector Name: QUINT, CRAIG On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 25255
Name of Operator: DUKE GAS COMPANY LLC
Address: 22500 COUNTY RD 24
City: VERNON State: CO Zip: 80755

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Cantrall, Diana		dcantrall@plainstel.coop	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253217	WELL	PR	01/01/2011	GW	125-07094	WARD 3-36	PR

General Comment:

Routine Inspection. Well is in a irrigated crop circle, seasonal access.

Location			
Lease Road:			
Type	Access		
comment:	Access covered with 8' corn		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign mounted on meter shed.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	Gas Meter Run	# 2	corrective date
Comment:	Central Battery f/Ward 3-36, Ward 13-36, 2520' SW by CR N, 40.18448, -102.58577		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:	<input type="text"/>		
Corrective Action:			Date:
Flaring:			
Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:			Date:

Inspected Facilities

Facility ID: 253217 Type: WELL API Number: 125-07094 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, Central Battery f/Ward 3-36, Ward 13-36, 2520' SW by CR N, 40.18448, - 102.58577](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT