

Inspected Facilities

Facility ID: 240757 Type: WELL API Number: 123-08545 Status: PR Insp. Status: PR

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 693507843in response to FIRR #403160579. Based on photos submitted by operator corrective actions appear to have been completed. (photos attached to FIRR)	silverr	10/27/2022