

## Inspection Photos

C8E Pipeline Leak

Spill/Release ID: 482258

Inspection Date: October 25, 2022



Photo #1 - 2019 COGCC GIS Online Map Viewer aerial photo depicting reported Spill/Release location (circled in black).



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

**Inspection Photos**  
**C8E Pipeline Leak**  
**Spill/Release ID: 482258**  
**Inspection Date: October 25, 2022**



**Photo #2 – Entrance to facility, looking north.**



**Photo #3 – View from northeast corner of pad, looking southwest over reported Spill/Release location.**

