

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840




Photo 1 – Wellhead – Unmarked Riser



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840



Photo 3 – ECD



Photo 4 – Tank Battery

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840



Photo 5 – Tank Battery Sign



Photo 6 – Combustor – Weeds

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840



Colorado Oil and Gas Conservation Commission
40.48236, -104.22139, 4620.3ft, 135°
10/25/2022 12:45:40

Photo 7 – Separator



Colorado Oil and Gas Conservation Commission
40.48221, -104.22105, 4636.9ft, 266°
10/25/2022 12:44:24

Photo 8 – Unmarked Risers

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840



Photo 9 – Rack



Photo 10 – Separator

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840



Photo 11 – Gas Meter Houses – Weeds in IR Area



Photo 12 – Weeds in IR Area

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840



Photo 13 – Weeds in IR Area



Photo 14 – Weeds in IR Area