

# Inspection Photos

October 20, 2022

Operator: Crowheart Energy LLC - #10776

Location ID: 313404

Location Name: BIG HOLE GULCH UNIT-611N94W/8SESW

Inspection Document #: 702800863

Moffat County, CO

SESW Section 8 T11N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: BIG HOLE GULCH UNIT-611N94W/8SESW

Location ID: 313404



10/20/22  
+40.921822,-107.972996  
98° E

**Photo 1.** Photo shows the access road has not been reclaimed.



10/20/22  
+40.920826,-107.973754  
3° N

**Photo 2.** Photo taken from the south shows an overview of the Location. It appears Final Reclamation has just been initiated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800863

## Inspection Photos

Location Name: BIG HOLE GULCH UNIT-611N94W/8SESW

Location ID: 313404



**Photo 3.** Photo taken from the Location entrance. It appears Final Reclamation has just been initiated. Gravel has been removed from the pad surface



**Photo 4.** Photo taken from the north. Flowline abandonment appears to be in process. Risers, methanol tank, and all other equipment must be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission


Department of Natural Resources

Inspection Number: 702800863

## Inspection Photos

Location Name: BIG HOLE GULCH UNIT-611N94W/8SESW

Location ID: 313404



**Photo 5.** Photo shows the pad surface. Compaction alleviation must be performed per Rule 1004.a.



**Photo 6.** Refer to Photo 5 comment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800863

## Inspection Photos

Location Name: BIG HOLE GULCH UNIT-611N94W/8SESW

Location ID: 313404



**Photo 7.** Photo taken from the east shows interim area vegetation. Additional reclamation may be necessary to meet 1004 vegetation requirements.



**Photo 8.** Refer to Photo 7 comment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800863

Inspection Photos  
Location Name: BIG HOLE GULCH UNIT-611N94W/8SESW  
Location ID: 313404



**Photo 9.** Photo taken to the south shows the reference area vegetation community.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800863