

Interim Reclamation and Stormwater Inspection

October 19, 2022

Operator: CIVITAS NORTH LLC - #10661

Location ID: 425364

Inspection Document #: 697504311

Weld County, CO

NWNW Section 14 T8N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WCR100 Group 14-11-8-61
Location ID: 425364



Photo 1. Photo taken from the eastern interim reclamation area, facing South. Photo illustrates the establishment of annual, weedy Kochia vegetation.



Photo 2. Photo taken from the eastern interim reclamation area, facing North. See comments under Photo 1.

Inspection Photos
Location Name: WCR100 Group 14-11-8-61
Location ID: 425364



Photo 3. Photo taken from the eastern interim reclamation area, facing West. See comments under Photo 1.



Photo 4. Photo taken from the eastern interim reclamation area, facing Northwest. See comments under Photo 1.

Inspection Photos
Location Name: WCR100 Group 14-11-8-61
Location ID: 425364



Photo 5. Photo taken from the southern interim reclamation area, facing Southeast. Photo illustrates both Kochia and some desirable plant species.



Photo 6. Photo taken from the southern interim reclamation area, facing Northwest. See comments under Photo 5.

Inspection Photos
Location Name: WCR100 Group 14-11-8-61
Location ID: 425364




Photo 7. Reference photo taken from the eastern interim reclamation area, facing South. Photo illustrates reference area vegetation to the left of the red-dashed line and interim areas to the right.



Photo 8. Reference photo taken from the eastern interim reclamation area, facing South. See comments under Photo 7.