

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Frei /A Pad

Location ID: 417777

Network: Oct 27, 2022 at 10:56:52 AM MD
Local: Oct 27, 2022 at 10:56:52 AM MD



Photo #8167 From entrance to location.

Network: Oct 27, 2022 at 10:56:55 AM MD
Local: Oct 27, 2022 at 10:56:55 AM MD



Photo #8168 From entrance to location.

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC Frei /A Pad
Location ID: 417777



Photo #8169 From entrance to location.



Photo #8170 From entrance to location.

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC Frei /A Pad
Location ID: 417777



Photo #8172 Location lacks stabilization.




Photo #8173 Location lacks stabilization.

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC Frei /A Pad
Location ID: 417777



Photo #8175 Location lacks stabilization.




Photo #8176 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Frei /A Pad

Location ID: 417777



Photo #8177 Insufficient tracking BMP at entrance to location.