

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms /L Pad

Location ID: 436713



Photo #8179 From entrance to location.



Photo #8180 From entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms /L Pad

Location ID: 436713



Photo #8181 From entrance to location.



Photo #8182 From entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms /L Pad

Location ID: 436713



**Photo #8184** Location lacks stabilization.



**Photo #8185** Location lacks stabilization.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms /L Pad

Location ID: 436713



**Photo #8186** Location lacks stabilization.



**Photo #8187** Insufficient tracking BMP at entrance to location.