

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad /Valley Farms J1

Location ID: 416703



Photo #8188 From entrance to location.



Photo #8189 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad /Valley Farms J1

Location ID: 416703



Photo #8190 Location lacks stabilization.



Photo #8191 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad /Valley Farms J1

Location ID: 416703



Photo #8192 Location lacks stabilization.



Photo #8198 Insufficient tracking BMP at entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad /Valley Farms J1

Location ID: 416703



Photo #8194 BMP's have not been implemented around stockpiled soils.



Photo #8196 BMP's have not been implemented around stockpiled soils.