

## Inspection Photos

**Location Name: TEP ROCKY MOUNTAIN LLC VALLEY FARMS-66S92W /15NENW**

**Location ID: 335534**



**Photo #8203 From entrance to location.**



**Photo #8204 From entrance to location.**

## Inspection Photos

**Location Name: TEP ROCKY MOUNTAIN LLC VALLEY FARMS-66S92W /15NENW**

**Location ID: 335534**



**Photo #8205 From entrance to location.**



**Photo #8206 From entrance to location.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VALLEY FARMS-66S92W /15NENW

Location ID: 335534



Photo #8209 Undesirable plant species in tank containment.



Photo #8210 Undesirable plant species in tank containment.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VALLEY FARMS-66S92W /15NENW

Location ID: 335534



**Photo #8208 Undesirable plant species in tank containment.**