

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16SENE

Location #: 302512



Photo #1

Bashor State AA 16-08 (05-123-29257) Wellsite

Temporarily Abandoned | TA

CA: Weeds need cleared



Photo #2

Bashor State AA 16-08, 16-01, 16-02, 16-07, 16-17,
16-18 Battery site

Abandoned: **ALL Equipment Removed**

Formerly served:

Bashor State 16-09, 16-22;

Plugged & Abandoned | PA