

Final Reclamation Inspection

October 26, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 319561

Inspection Document #: 697504319

Weld County, CO

NESE Section 18 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: SCHWALM-ULLMANN FARMS #18-1

Location ID: 319561



Photo 1. COGCC GISOnline aerial imagery from 2019 illustrates the well location, flowline and associated offsite tank battery. Form 44 Abandonment Notice has not been submitted.

Inspection Photos
Location Name: SCHWALM-ULLMANN FARMS
#18-1
Location ID: 319561



Photo 2. Photo taken from the associated offsite tank battery, facing South. Photo illustrates all equipment has been removed and the tank battery is not within crop production.



Photo 3. Photo taken from the associated offsite tank battery, facing West. See comments under Photo 2.

Inspection Photos
Location Name: SCHWALM-ULLMANN FARMS
#18-1
Location ID: 319561



Photo 4. Photo taken from the well location, facing East. Photo illustrates all equipment has been removed and the well location is not within crop production.