



Sediment discharge cleaned up and area has been reseeded and straw mulched. Standing at the southeast corner looking northwest at the pad.





Dirt work completed to remove rill erosion and area has been reseeded and straw mulched.  
Standing off the southeast edge of pad looking west.





Bare area has been reseeded and straw mulched. Standing on eastern edge of pad, looking southeast.