



Interim reclamation has commenced. Pad has been pulled back and seeding with straw mulching has been completed. Standing near entrance, looking north.



Interim reclamation has commenced. Pad has been pulled back and seeding with straw mulching has been completed. Standing near entrance, looking west.



Interim reclamation has commenced. Pad has been pulled back and seeding with straw mulching has been completed. Standing near southeast corner, looking west.



Interim reclamation has commenced. Pad has been pulled back and seeding with straw mulching has been completed. Standing near southwest corner, looking north.



Interim reclamation has commenced. Pad has been pulled back and seeding with straw mulching has been completed. Standing near northwest corner, looking east.