

Inspection Photos

API: 073-06250

Operator: MAGPIE OPERATING INC

Inspection Date: 10/25/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06250 | Date: 10/25/2022

Inspection Photos



Photo 1. Drone aerial photo facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06250 | Date: 10/25/2022

Inspection Photos



Photo 2. Drone aerial photo facing southwest toward the location. There are still areas that have not established desirable vegetation cover. The area in lower left inadequate desirable vegetation and undesirable weeds. The brown vegetation is undesirable weeds → Russian thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06250 | Date: 10/25/2022

Inspection Photos



Photo 3. Drone aerial photo facing north toward the location. There are still areas that have not established desirable vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06250 | Date: 10/25/2022