

**Inspection Photos**  
**Location Name: State Antelope T-1 PAD**  
**Location ID: 440869**



**Photo 1 – Signs at Entrance**




**Photo 2 – Wellheads**

**Inspection Photos**  
**Location Name: State Antelope T-1 PAD**  
**Location ID: 440869**



**Photo 3 – Gas Lift Injection Meter House**



**Photo 4 – Unmarked Riser at Tank**



**Inspection Photos**  
**Location Name: State Antelope T-1 PAD**  
**Location ID: 440869**



**Photo 5 – Unmarked Riser at Separators**