

Inspection Photos

Location Name: Champlin 75 AMOCO J 1

Location ID: 319932

Oct 27, 2022 at 2:32:04 PM
39.851119,-104.608740
Adams County
COGCC



Pic 1 wellhead

Oct 27, 2022 at 2:31:27 PM
39.858035,-104.597836
Adams County
COGCC



Pic 2 tanks, weeds unmanaged

Inspection Photos

Location Name: Champlin 75 AMOCO J 1

Location ID: 319932

Oct 27, 2022 at 2:31:43 PM
39.851170,-104.609151
Adams County
COGCC



Pic 3 separator, gas meter run



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources