

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16SENW

Location #: 310240



Photo #1

Bashor State AA 16-6 (05-123-26118) Wellsite

Temporarily Abandoned | TA

CA: Weeds need cleared



Photo #2

Bashor State AA 16-5, 16-3, 16-04, 16-6, 16-12,
16-19, 16-20 Battery site

Abandoned: ALL Equipment Removed