

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NWNW

Location #: 302508



Photo #1

Bashor State AA 16-04 (05-123-29253) Wellsite

Temporarily Abandoned | TA

CA: Weeds need cleared



Photo #2

**Bashor State AA 16-5, 16-3, 16-04, 16-6, 16-12,
16-19, 16-20 Battery site**

Abandoned: ALL Equipment Removed