

Interim Reclamation and Stormwater Inspection

Date: 10/11/2022

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 462872

Inspection Document #: 696105532

Weld County, CO

SESW Section 25 T9N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PEGGY 2501 Pad
Location ID: 462872



Photo 1. Taken near entrance facing east. Photo illustrates annual weedy vegetation (kochia) observed in perimeter ditch.

Inspection Photos
Location Name: PEGGY 2501 Pad
Location ID: 462872



Photo 2. Taken from eastern portion, facing west. Photo illustrates fencing material in ditch.

Inspection Photos
Location Name: PEGGY 2501 Pad
Location ID: 462872



Photo 3. Taken from eastern portion, facing southeast. See comments in photo 1.

Inspection Photos
Location Name: PEGGY 2501 Pad
Location ID: 462872



Photo 4. Taken from eastern portion, facing northwest. See comments in photo 1.

Inspection Photos
Location Name: PEGGY 2501 Pad
Location ID: 462872



Photo 5. Taken from northern portion of location, facing west. Photo illustrates topsoil stockpile has failed to revegetate; some annual weedy vegetation observed, outlined in red.

Inspection Photos
Location Name: PEGGY 2501 Pad
Location ID: 462872



Photo 6. Facing west. See comments in photo 5.

Inspection Photos
Location Name: PEGGY 2501 Pad
Location ID: 462872



Photo 7. Taken from western portion of stockpile, facing east. See comments in photo 5.

Inspection Photos
Location Name: PEGGY 2501 Pad
Location ID: 462872



Photo 8. Taken from northwestern corner, facing southwest. See comments in photo 1.