

Final Reclamation and Stormwater Inspection

Date: 10/24/2022

Operator: SHELL OIL COMPANY - 78100

Location ID: 387762

Inspection Document #: 696105552

Logan County, CO

SWSE Section 26 T8N R54W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: L C HOXIE
Location ID: 387762



Photo 1. Taken from location, facing West. Photo shows non-uniform vegetation cover resulting in bare soil; location is not reflective of reference areas.

Inspection Photos
Location Name: L C HOXIE
Location ID: 387762



Photo 2. Facing south, see comments in Photo 1.

Inspection Photos
Location Name: L C HOXIE
Location ID: 387762



Photo 3. Facing north, see comments in Photo 1.

Inspection Photos
Location Name: L C HOXIE
Location ID: 387762



Photo 4. Facing south, see comments in Photo 1.

Inspection Photos
Location Name: L C HOXIE
Location ID: 387762



Photo 5. Reference area photo taken northeast of location facing northeast.