

Final Reclamation and Stormwater Inspection

Date: 10/24/2022

Operator: HRBEK* RANDALL L - 41365

Location ID: 387770

Inspection Document #: 696105554

Logan County, CO

SESW Section 26 T8N R54W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LUTHER #1
Location ID: 387770



Photo 1. Taken from access road, facing south. Photo illustrates the access road has not been reclaimed with presence of road base/gravel.

Inspection Photos
Location Name: LUTHER #1
Location ID: 387770



Photo 2. Taken near well location, facing west. Photo illustrates non-uniform vegetation cover and pipe sticking out of the ground.

Inspection Photos
Location Name: LUTHER #1
Location ID: 387770



Photo 3. Close up photo of well location. See comments in Photo 2.

Inspection Photos
Location Name: LUTHER #1
Location ID: 387770



Photo 4. Facing northeast, see comments in Photo 2.

Inspection Photos
Location Name: LUTHER #1
Location ID: 387770



Photo 5. Taken west of location, facing west. Background illustrates pit location is predominantly undesirable vegetation (e.g. kochia) outlined in red.

Inspection Photos
Location Name: LUTHER #1
Location ID: 387770



Photo 6. Taken south of location, facing west. Photo illustrates reference area.