

Inspection Photos
Location Name: Flanders Industries 1
Location ID: 319864



Photo#1. Tanks.

Photo#2. Stained soil under crude tank.

Inspection Photos
Location Name: Flanders Industries 1
Location ID: 319864



Photo#3. No bull plug in load out bucket.



Photo#4. Stained soil under valve on oil tank.

Inspection Photos
Location Name: Flanders Industries 1
Location ID: 319864



Photo#5. P/W tank.



Photo#6. Stained soil on back side of P/W tank.

Inspection Photos
Location Name: Flanders Industries 1
Location ID: 319864



Photo#7. Separator.

Photo#8. Pit.

Inspection Photos
Location Name: Flanders Industries 1
Location ID: 319864



Photo#9. Pit.



Photo#10. Pump Jack.