

Inspection Photos
Location Name: UPRR-Linnebur 1
Location ID: 319819



Photo#1 Tanks.



Photo#2 Stained soil on back side of load off bucket.

Inspection Photos
Location Name: UPRR-Linnebur 1
Location ID: 319819



Photo#3. Separator.



Photo#4. Stained soil on back side of separator.

Inspection Photos
Location Name: UPRR-Linnebur 1
Location ID: 319819



Photo#5. Pit.



Photo#6. Pit.

Inspection Photos
Location Name: UPRR-Linnebur 1
Location ID: 319819



Photo#7. Pump Jack.