

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403206073

Date Received:
10/24/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>.General</u>		<u>sjninspections@ikavenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500465

Inspection Date: 09/21/2022

FIR Submit Date: 09/21/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325241

Location Name: PAN AM FEE GAS UNIT B- N33N8W Number: 23SENW County: LA PLATA

Qtrqtr: SENW Sec: 23 Twp: 33N Range: 8W Meridian: N

Latitude: 37.092501 Longitude: -107.690720

FACILITY - API Number: 05-067-00 Facility ID: 214381

Facility Name: PAN AMERICAN FEE B Number: 1

Qtrqtr: SENW Sec: 23 Twp: 33N Range: 8W Meridian: N

Latitude: 37.092501 Longitude: -107.690720

CORRECTIVE ACTIONS:

1 CA# 164718

Corrective Action:

Date: 10/21/2022

Response:

Date of Completion: 09/28/2022

Operator Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500465 has been satisfactorily completed, pending reinspection.

2 CA# 164719

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C

Date: 10/07/2022

Response: CA COMPLETED

Date of Completion: 10/05/2022

Operator Comment: Repair and add wattles to erosion channels.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500465 has been satisfactorily completed, pending reinspection.

OPERATOR COMMENT AND SUBMITTAL

Comment: CA complete. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 10/24/2022 10:28:09 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403206073	FIR RESOLUTION SUBMITTED
403206082	Pan American Fee B1, CA Complete Photos

Total Attach: 2 Files