

# Inspection Photos

October 31, 2022

Operator: Argali Exploration Company - #3975

Location ID: 313044

Location Name: STATE-69N90W/31SWSW

Inspection Document #: 702800868

Moffat County, CO

SWSW Section 31 T9N R90W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATE-69N90W/31SWSW  
Location ID: 313044



**Photo 1.** Photo taken from the east shows an overview of the Location. Note Canada thistle (red circle) (List B Noxious).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800868



Inspection Photos  
Location Name: STATE-69N90W/31SWSW  
Location ID: 313044



**Photo 2.** Photo shows production equipment. Secondary containment for the methanol tank is degraded and insufficient. Signs on Location have been updated with current Operator information.



**Photo 3.** Photo shows production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800868



Inspection Photos  
Location Name: STATE-69N90W/31SWSW  
Location ID: 313044



**Photo 4.** Photo shows an example of Canada thistle (List B Noxious) on Location.



**Photo 5.** Photo shows an unmarked anchor.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800868



Inspection Photos  
Location Name: STATE-69N90W/31SWSW  
Location ID: 313044



**Photo 8.** Photo shows areas of the Location not necessary for production operations are vegetated with perennial grasses and shrubs.

