

Inspection Photos

October 31, 2022

Operator: Argali Exploration Company - #3975

Location ID: 313030

Location Name: STATE-69N91W/36SWSE

Inspection Document #: 702800873

Moffat County, CO

SWSE Section 36 T9N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE-69N91W/36SWSE
Location ID: 313030



Photo 1. Photo taken from the center of the Location shows an overview of the production area. Sign has been updated with current Operator information but remains in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800873

Inspection Photos
Location Name: STATE-69N91W/36SWSE
Location ID: 313030



Photo 2. Photo taken from the southwest of the Location shows the cut slope has not been properly reclaimed; vertical cut must be recontoured to match the surrounding landscape and stabilized to prevent erosion.



Inspection Photos
Location Name: STATE-69N91W/36SWSE
Location ID: 313030



Photo 3. Photo taken from the northwest of the Location shows the cut slope has not been properly reclaimed; vertical cut must be recontoured to match the surrounding landscape and stabilized to prevent erosion.



Photo 4. Refer to Photo 3 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800873

Inspection Photos
Location Name: STATE-69N91W/36SWSE
Location ID: 313030



Photo 5. Photo shows erosion occurring in the fill slope at the east of the Location. The hole was approximately 8 by 9 feet wide and 3 feet deep. Arrow indicates the deepest part of the hole which was approximately 10 feet deep.



Photo 6. Photo shows erosion occurring in the fill slope at the east of the Location. Arrow indicates the deepest part of the hole which was approximately 10 feet deep.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800873