

Inspection Photos and Issue Report

11/1/2022

Operator: GUNNISON ENERGY LLC - 10515

Location #324464

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location #324464



Photo 1: Photo taken from west end of the Location, and shows areas of the former Ragged Mountain Compressor Facility. Photos shows various equipment (pipe, risers, etc..) that appear to have been associated with the facility remain on site. This issue is being forwarded to the COGCC Environmental Group.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location #324464



Photo 2: Photos show secondary containment BMPs at the tank battery have been installed or repaired.



Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location #324464



Photo 3: Photo shows soil stockpile stored on the northeast end of the Location has been removed.



Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location #324464



Photo 4: Photos taken from the interim areas on the north/northwest end of the Location. Photos show areas not needed for production operations. Previous inspections required Operator to conduct interim reclamation by 6/7/2021. Unable to find evidence that interim reclamation work has been completed; Operator on site also confirmed that reclamation work has not yet been performed.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location #324464



Photo 5: Photo taken from off-site areas northwest of the Location. Photo shows areas where Operator improperly stored various unused trash/debris/equipment. Disturbed areas are apparent; noxious weed establishment observed.