

# Inspection Photos

October 31, 2022

Operator: Argali Exploration Company - #3975

Location ID: 313040

Location Name: FEDERAL SANDWASH-68N91W/1NWNE

Inspection Document #: 702800875

Moffat County, CO

NWNE Section 1 T8N R91W

Anna O'Malley  
Reclamation Specialist, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FEDERAL SANDWASH-68N91W/1NWNE  
Location ID: 313040



**Photo 1.** Photo taken from the southwest shows an overview of the Location. Decommissioned facilities (foreground) require site investigation, remediation, and closure followed by interim reclamation after compliance with 915-1 standards. Remaining pipe must be removed. Unused tank must be removed.





## Inspection Photos

Location Name: FEDERAL SANDWASH-68N91W/1NWNE

Location ID: 313040



**Photo 2.** Photo taken from the southwest shows a pipe remaining at the produced water tank facility. Pipe must be removed.



**Photo 3.** Photo taken from the northeast of the Location shows a decommissioned partially buried tank facility. Decommissioned facilities require site investigation and remediation followed by interim reclamation after compliance with 915-1 standards. Note also, unused tank.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800875



## Inspection Photos

Location Name: FEDERAL SANDWASH-68N91W/1NWNE

Location ID: 313040



**Photo 4.** Photo taken from the northwest. The methanol tank secondary containment lacks wildlife protection BMPs. The tank label is inaccurate; tank capacity reads 500 BBLs.



**Photo 5.** Photo shows the wellhead. Wellhead signage does not comply with Rule 605.d. Photo also shows trash around the wellhead.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800875



## Inspection Photos

Location Name: FEDERAL SANDWASH-68N91W/1NWNE

Location ID: 313040



**Photo 6.** Photos shows a bull thistle (List B Noxious) which has gone to seed and a basal rosette.



**Photo 7.** Photo shows Canada thistle (List B Noxious).



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800875



## Inspection Photos

Location Name: FEDERAL SANDWASH-68N91W/1NWNE

Location ID: 313040



**Photo 8.** Photo shows an anchor marker in disrepair.



**Photo 9.** Photo taken from the southwest of the Location shows rill erosion occurring in bare, unprotected soils.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800875



## Inspection Photos

Location Name: FEDERAL SANDWASH-68N91W/1NWNE

Location ID: 313040



**Photo 10.** Photo taken from the east of the Location show fill slopes and interim areas vegetated with perennial grasses. Photo also shows similarity with reference area vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800875