

Inspection Photos
Location Name: Vera 1
Location ID: 318556



Photo 1 – Separator




Photo 2 – Unmarked Risers

Inspection Photos
 Location Name: Vera 1
 Location ID: 318556





Photo 3 – Unmarked Risers

Photo 4 – Gas Meter Calibration Card

Inspection Photos
Location Name: Vera 1
Location ID: 318556



Photo 5 – NFPA Label

Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Vera 1
Location ID: 318556



Photo 7 – Tank Battery



Photo 8 – Pumping Unit

Inspection Photos
Location Name: Vera 1
Location ID: 318556



Photo 9 – Wellhead

Photo 10 – Wellhead Sign

Inspection Photos
Location Name: Vera 1
Location ID: 318556



Photo 11 – Gas Engine