

Inspection Photos
Location Name: State 8-7
Location ID: 326971



Photo 1 – Wellhead



Photo 2 – Pumping Unit

Inspection Photos
Location Name: State 8-7
Location ID: 326971



Photo 3 – Wellhead Sign



Photo 4 – Separator

Inspection Photos
Location Name: State 8-7
Location ID: 326971




Photo 5 – Tank Battery



Photo 6 – Back Valve – Stained Soil cleaned up

Inspection Photos
Location Name: State 8-7
Location ID: 326971



Photo 7 – Tank Labels – Content Label