

# Final Reclamation Inspection

November 2, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 323453

Inspection Document #: 697504325

Weld County, CO

SESE Section 30 T4N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HALVERSON 1  
Location ID: 323453



**Photo 1.** COGCC drone aerial imagery taken on 11/2/2022 illustrating the active remediation projects related to the Halverson 1 well. Photo illustrates an open remediation for the wellhead and tank battery.



Inspection Photos  
Location Name: HALVERSON 1  
Location ID: 323453



**Photo 2.** COGCC drone aerial imagery taken on 11/2/2022 illustrating the active remediation projects related to the Halverson 1 well. Photo illustrates an open remediation for the wellhead and tank battery. Photo illustrates the adjacent cropland is fallow and will likely go back into crop production next Spring.

Inspection Photos  
Location Name: HALVERSON 1  
Location ID: 323453



**Photo 3.** Photo taken from the central location, facing East. Photo illustrates the open excavation for the tank battery which has been fenced off.



**Photo 4.** Photo taken from the central location, facing West. See comments under Photo 3.

Inspection Photos  
Location Name: HALVERSON 1  
Location ID: 323453



**Photo 5.** Photo taken from the tank battery excavation, facing East. Photo illustrates netting over the groundwater portion and sand to the north of the groundwater.



**Photo 6.** Photo taken of the eastern tank battery sidewall. Photo illustrates sidewall impacts appear to be evident.

Inspection Photos  
Location Name: HALVERSON 1  
Location ID: 323453



**Photo 7.** Photo taken from the wellhead excavation, facing Northwest. Photo illustrates netting over the excavation.



**Photo 8.** Photo taken from the north central location, facing West. Photo illustrates a stockpile of sand, not topsoil.