

Inspection Photos and Issue Report

11/1/2022

Operator: GUNNISON ENERGY LLC - 10515

Location #412922

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Photo 1: Photos taken from the Location entrance. Photos at above from the 4/4/2022 inspection and show the Location signage. Photo bottom right shows location signage has been removed. Photo bottom right also shows that Operator has attempted to install signage required per the Delayed IR Variance conditions (orange arrow), however sign has not been properly secured and is now debris. Sign is also made of poor quality material and is deteriorating.



Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location #412922



Photo 2: Photo example showing anchor marker not in proper functioning condition.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location #412922



Photo 3: Photo taken from the north end of the Location. Photo shows soils stockpiles with missing BMPs to protect stockpiles from wind and water erosion, as well as to minimize erosion, degradation and sediment transport