


Inspection Photogs  
Location Name: REA 18U-03 2  
Location ID: 306754



IMG 01  
Well sign



IMG 02  
Location overview



03Nov22 10:38 Ad-hoc  
4820 SH-172, Durango CO 81303, US © 03-Nov-22 10:38:03

**IMG 03**  
**Exhaust muffler**



03Nov22 10:38 Ad-hoc  
4820 SH-172, Durango CO 81303, US © 03-Nov-22 10:38:30

**IMG 04**  
**Rig anchor**



**IMG 05**  
**Tank sign**