

Inspection Photos

October 31, 2022

Operator: Argali Exploration Company - #3975

Location ID: 313236

Location Name: FEDERAL-68N91W/1NESE

Inspection Document #: 702800879

Moffat County, CO

NESE Section 1 T8N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FEDERAL-68N91W/1NESE
Location ID: 313236



Photo 1. Photo shows production areas to the west.



Photo 2. Photo shows production areas to the east. Note unused tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800879

Inspection Photos
Location Name: FEDERAL-68N91W/1NESE
Location ID: 313236



Photo 3. Photo taken from the west. The methanol tank secondary containment lacks wildlife protection BMPs. Tank label is faded. Contact numbers on tank are outdated.



Photo 4. Photo shows an unused tank being stored at the southeast of the Location.

Inspection Photos
Location Name: FEDERAL-68N91W/1NESE
Location ID: 313236



Photo 5. Photo shows trash/debris adjacent to the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800879

Inspection Photos
Location Name: FEDERAL-68N91W/1NESE
Location ID: 313236



Photo 6. Photo shows the wellhead. Wellhead sign lacks the API number.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800879

Inspection Photos
Location Name: FEDERAL-68N91W/1NESE
Location ID: 313236



Photo 7. Photo shows an example of bull thistle (List B Noxious) found throughout the Location. Photo also shows an anchor marker in disrepair (left). Anchor is marked (right), marker to left is now trash/debris.



Photo 8. Photo shows an example of Canada thistle (List B Noxious) found throughout the Location.

Inspection Photos
Location Name: FEDERAL-68N91W/1NESE
Location ID: 313236



10/31/22
+40.678538,-107.548058
19° N

Photo 9. Photo shows interim areas at the north of the Location are well vegetated with perennial grasses.



10/31/22
+40.678033,-107.547199
8° N

Photo 10. Photo shows interim areas at the south of the Location are well vegetated with perennial grasses.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800879