

Inspection Photos and Issue Report

11/1/2022

Operator: SG INTERESTS I LTD - 77330

Location #429333

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location #429333



Photo 1: Location signage detailing variance information. “Reclamation no later than” date requires updating to reflect new variance termination date of 9/11/2024.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location #429333



Photo 2: Photos taken from the south end of the Location. Photos provide an overview of the location from north to northeast.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location #429333



Photo 3: Photo taken from the southeast end of the Location. Photo shows areas where Operator appears to have installed a slope drain. Soils on the slopes have been left bare and at risk to erosion degradation.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location #429333



Photo 4: Photo taken from the perimeter berm on the northwest end of the Location. Photo shows cracks along the perimeter of the location are beginning to re-develop.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location #429333



Photo 5: Photo taken from the perimeter berm on the southeast end of the Location. Photo shows cracks along the perimeter of the location are beginning to re-develop.