

# Inspection Photos

October 31, 2022

Operator: Argali Exploration Company - #3975

Location ID: 313027

Location Name: STATE-69N91W/36SWSW

Inspection Document #: 702800885

Moffat County, CO

SWSW Section 36 T9N R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: STATE-69N91W/36SWSW  
Location ID: 313027



**Photo 1.** Photo taken from the northwest shows an overview of the Location.



Inspection Photos  
Location Name: STATE-69N91W/36SWSW  
Location ID: 313027



Photo 2. Photo shows separator equipment.



Photo 3. Photo shows the wellhead.



Inspection Photos  
Location Name: STATE-69N91W/36SWSW  
Location ID: 313027



**Photo 4.** Photo taken from the north shows equipment remaining at the pit area. Pit has been closed, equipment is no longer in use and must be removed.

Inspection Photos  
Location Name: STATE-69N91W/36SWSW  
Location ID: 313027



**Photo 5.** Photo shows Canada thistle (List B Noxious) which is found on otherwise unvegetated portions of the eroding cut slope.



Inspection Photos

Location Name: STATE-69N91W/36SWSW

Location ID: 313027



**Photo 6.** Photo shows the cut slope at the northeast of the Location is bare and unprotected. Rill erosion is evident throughout unvegetated portions of cut slopes.



**Photo 7.** Refer to Photo 6 comment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800885