

Inspection Photos

Location Name: SHOEMAKER A-66N64W/12NENE

Location #: 306566



Photo #1
Shoemaker A 12-1 (05-123-24923) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 25 yds.



Photo #2
Storer A 12-2 Battery site
Inactive / Shut-down
Formerly served:
Shoemaker A 12-1;
Plugged & Abandoned | PA