

Inspection Photos
Location Name: Shoemaker/AA07-65HN Multi
Location #: 306586



Photo #1

Shoemaker A 12-9 (05-123-24952) Wellsite
Temporarily Abandoned | TA



Photo #2

Shoemaker A 12-8, 12-7, 12-9, 12-17 Battery site
Active

Equipment documented: Loc. # 306584