

Inspection Photos
Location Name: SCHRANT-66N64W/12NESW
Location #: 332431



Photo #1
Schant 23-12 (05-123-22290) Wellsite
Producing | PR



Photo #2
Schant 24-12, 23-12, Lapp 33-12 Battery site
Active
Equipment documented: Loc. # 332432