

Inspection Photos
Location Name: Harper USX EE27-07D Multi
Location ID: 423538



Photo 1: Wellhead Sign



Photo 2: Weeds/debris, unused equipment

Inspection Photos
Location Name: Harper USX EE27-07D Multi
Location ID: 423538




Photo 3: Wellhead Sign



Photo 4: Weeds

Inspection Photos
Location Name: Harper USX EE27-07D Multi
Location ID: 423538




Photo 5: Wellhead Sign



Photo 6: Weeds/debris

Inspection Photos
Location Name: Harper USX EE27-07D Multi
Location ID: 423538




Photo 7: Wellhead Sign



Photo 8: Weeds

Inspection Photos
Location Name: Harper USX EE27-07D Multi
Location ID: 423538



Photo 9: Wellhead Sign



Photo 10: Weeds

Inspection Photos
Location Name: Harper USX EE27-07D Multi
Location ID: 423538



Photo 11: Wellhead Sign



Photo 12: Weeds

Inspection Photos
Location Name: Harper USX EE27-07D Multi
Location ID: 423538



Photo 13: Tank Battery



Photo 14: Equipment